



Power supply and voltage measurement terminals

## Wiring diagram


1. Directly powered wiring diagrams for gauge 1A or 10A headers




2. Independent power supply wiring diagram for gauge 1A or 10A head



3. Independent power supply wiring diagram for gauge head of range 50A




4. Wiring diagram of direct power supply for gauge head 50A or 100A



## High voltage wiring diagram

1. Wiring diagram of direct power supply for the head of gauge 1A or 10A



2. Wiring diagram of direct power supply for gauge head 50A or 100A

